

Mariners are advised that initial cable repair works in the Mostyn area have been completed, remaining work remains to install cable protection which will take place within the next few weeks.

Meanwhile the cable is exposed on the seabed between the following locations

	Eastings Northings	Latitude	Longitude
Position A	461968.79E, 5917775.39N	53° 24.4606989'N,	003° 35.3261484'W
Position B	461513.97E, 5917343.79N	53° 24.2259614'N	003° 34.7334864'W

Mariners are requested to avoid any seabed activity including anchoring in this area until further notice.

Contact Information for further information

Name	Company	Position	Phone	Email
David Brown	Balfour Beatty	Project Manager	+44 7961 2130181	David.brown@thornbeckdesign.com