

RWE

RF14, RF18 & RF07 Jack up Vessel Generator Campaign - Notice to Mariners:- 03-2025

Project	Rhyl Flats Proactive Generator exchange
Date of Issue	11/03/2026
Notice number / reference	Rhyl Flats NotM 01-2026
Location	53°22.771'N 003°38.620'W
Activity	Jack Up Vessel heavy lift works
Scheduled start date	20/03/2026
Expected End Date	10/04/2026
Issued by	Daniel Price
Kingfisher Bulletin download link	https://kingfisherbulletin.org/notice-map?noticelid=5764
Fisheries Enquiries Contacts:	Jim Andrews - jim@awjmarine.co.uk
General Enquiries Contacts:	Dan Price - Production Manager Ops_RhylFlats@rwe.com Thomas Davies - Operations Engineer Ops_RhylFlats@rwe.com

Overview

Activities

All mariners are advised that MPI Adventure will be carrying out maintenance operations at Rhyl flats Offshore Wind Farm from 20/03/2026 until 10/04/2026. These dates are subject to weather and sea conditions. Specific coordinates of locations where works occur are found below.

Requirements of Mariners

“Mariners must observe the safety zone of 500m when the MPI Adventure is attached or anchored next to RF14, RF18 & RF07. It is also requested that mariners observe a distance of at least 500m when MPI Adventure is manoeuvring into position for the safety of all sea users

operating within the wind farm, and to ensure MPI Adventure can safely position itself without negative interactions with sea users or their equipment.

Vessel Information

Vessel Information		Picture
Name	Adventure	
IMO	9530084	
MMSI	245924000	
Call Sign	PCKV	
Length (m)	138.5m	
Breadth (m)	41m	
Draught (m)	5.50m	
AIS	Class A	
Positioning Equipment	DP2 Kongsberg K-Pos DP-21	

Works Locations

Location	Coordinates				Works type
	Lat DDM	Lon DDM	Northing	Easting	
RF14	53°22.771'N	003°38.620'W	388,222	290,761	Generator Replacement
RF18	53°22.388'N	003°36.925'W	387,469	292,624	Generator Replacement
RF07	53°22.903'N	003°36.600'W	388,416	293,006	Generator Replacement

Additional information

All mariners and their equipment are requested to remain at least 500m from all infrastructure at all times. CTVs will be regularly on site and mariners should keep a safe working distance of 500 m from these vessels where possible. <https://kingfisherbulletin.org/notice-map?noticeld=5764> to Sea Users Guide pdf for download.